HABS No. IN-163

Solomon Fussell House south side of State Route 38, 3 miles east of Pendleton Pendleton vicinity Madison County Indiana

HABS IND, 48-PENIV,

REDUCED COPIES OF MEASURED DRAWINGS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey National Park Service Department of the Interior Washington, D.C. 20240 Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS IND, 48-PEN.V,

ARCHITECTURAL DATA FORM

1	STATE	COUNTY		TOWN OR VI	CINITY	
	Indiana	Madison		Pendleto	n vicinity	
I	TORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)				HABS NO.	
I	olomon Fussell House				IN-163	
	SECONDARY OR COMMON NAMES OF S	CONDARY OR COMMON NAMES OF STRUCTURE				
ŀ	COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)					
	outh side of State Route 38, 3 miles east of Pendleton					
ŀ	ATE OF CONSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (INCLUDE SOURCE) Unknown; original owner/builder was					
l	unknown; original owner/builder was Solomon Fussell				uilder was	
ŀ	SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)					
	Constructed ca. 1832, this house is one of the earliest extant log buildings in Indiana					
	and an interesting example of a vernacular dwelling which evolved over time.					
ŀ	STYLE (IF APPROPRIATE)					
	Vernacular					
	MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)					
	Log, with frame additions					
	SHAPE AND OIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)					
	Rectangular, with additions to the south side; $65'-7" \times 26'-5"$; $2-1/2$ stories; gable roof					
İ	EXTERIOR FEATURES OF NOTE					
I						
l						
ľ	INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)					
	Finished wood planking on interior partitions					
l	- · · · · · · · · · · · · · · · · · · ·					
ŀ	MAJOR ALTERATIONS AND ADDITIONS WITH DATES					
l	Main facade of the house was originally the south facade, which faced the road which once ran to the south of the house. When the road was re-routed to the north of the house, the					
۱	entrance facade was reoriented. Sometime after this, the additions were made to the south.					
ŀ	No exact dates known for these changes. PRESENT CONDITION AND USE					
ŀ	OTHER INFORMATION AS APPROPRIATE					
ļ	OTHER INCORMATION AS AFFROERIATE					
1	SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)					
	Slade, Thomas M. Historic American Buildings Survey in Indiana. 1983.					
	COMPILER, AFFILIATION				DATE	
Druscilla J. Null, HABS 7/17/84					7/17/84	